

HI-VIS Heated Jacket Size Chart



KP1304, KP1305, KP1306, KP1307
Measurements in cm

	M	L	XL	XXL
A. Length	72	74	76	78
B. Chest	132	136	140	144
C. Hem Stretched	126	130	134	138
C. Hem Loose	100	104	108	112
D. Shoulder	52	54	56	58
E. Length of Sleeve	66	67	68	69
F. Width of Sleeve	28	29	30	31
G. Collar	57	57	59	59
H. Hood Height	40	40	42	42
I. Hood Width	27	27	28	28